



BOTH THE 1780 SURVEY OF ST. JOHN AND THE OXFORD MAP OF ST. JOHN'S PUBLISHED IN 1800 SHOW A BUILDING ON THE SITE OF THE EXISTING GREAT HOUSE. THE PRESENT BUILDING INCORPORATES SEVERAL LATE ADDITIONS FROM THIS CENTURY. THE DATE OF CONSTRUCTION OF THE OLDER MASONRY STRUCTURE HAS NOT BEEN DETERMINED. CORNICE & OTHER ARCHITECTURAL DETAILS IMPLY AN EARLY 19TH CENTURY DATE.



RECORDED BY THE NATIONAL PARK SERVICE, UNITED STATES DEPARTMENT OF THE INTERIOR
MEASURED DEC. 1962 AND DRAWN JAN. 1963 AND NOVEMBER OF 1964 UNDER THE DIRECTION OF
CHIEF ARCHITECT ROBERT E. SMITH, EASTKUTO OFFICE, DESIGN & CONSTRUCTION BY ARCH. F.C. SIESING.

DUE TO INSUFFICIENT INFORMATION AT THE TIME OF EDITING, THIS MATERIAL MAY NOT CONFORM TO HABS OR HAER STANDARDS.

FC. GJESSING NOV. 1964

FIELD OFFICE, VIRGIN ISLANDS NATIONAL PARK
UNDER DIRECTION OF UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE, BRANCH OF PLANS AND DESIGN

ESTATE MARY POINT

NAME OF STRUCTURE
"GREAT HOUSE"
SAINT JOHN


VIRGIN ISLANDS

SURVEY NO.	VI-159
------------	--------

HISTORIC AMERICAN
BUILDINGS SURVEY
SHEET 1 OF 6 SHEETS

LIBRARY OF CONGRESS

DUE TO INSUFFICIENT INFORMATION AT THE TIME OF EDITING, THIS MATERIAL MAY NOT CONFORM TO HABS OR HAER STANDARDS.



P.C. GIBBSING 10064

FIELD OFFICE, VIRGIN ISLANDS NATIONAL PARK
UNDER DIRECTION OF UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE, BRANCH OF PLANS AND DESIGN

ESTATE MARY POINT

NAME OF STRUCTURE
"GREAT HOUSE"
SAINT JOHN


VIRGIN ISLANDS


SURVEY NO.
VI-153

HISTORIC AMERICAN
BUILDINGS SURVEY
SHEET 2 OF 6 SHEETS


LIBRARY OF CONGRESS
INDEX NUMBER

DUE TO INSUFFICIENT INFORMATION AT THE TIME OF EDITING, THIS MATERIAL MAY NOT CONFORM TO HABS OR H&R STANDARDS.





DUE TO INSUFFICIENT INFORMATION AT THE TIME OF FIELDWORK, DRAWINGS MAY NOT CONFORM TO HABS OR HAKN STANDARDS.



SECTION C-C
SCALE 1/4" = 1'-0"

NOTE:
INTERIOR MASONRY WALLS OF MAIN HOUSE ARE
PARSED ONLY, THERE ARE REMNAITS OF NAILING
STRIPS SET IN THE MASONRY AND THE WALLS WERE
AT ONE TIME COVERED EITHER WITH CANVASS OR
THIS BOARDING OF SOME KIND.
THE REMAINS OF THE TRAY CEILING STILL IN PLACE
ARE OF COMPOSITION BOARD WITH WOOD TRIM, TRACES
ON BATTENS 4 TIES INDICATE THAT THE PRESENT ONE
IS THE SECOND OR THIRD ON THE EXISTING NAILERS.



SECTION B-B
SCALE 1/4" = 1'-0"

DUE TO INSUFFICIENT INFORMATION AT THE
 TIME OF EDITING, THIS MATERIAL MAY NOT
 CONFORM TO HABS OR HAER STANDARDS.

F.C. GLESSING NOV. 1964

FIELD OFFICE, VIRGIN ISLANDS NATIONAL PARK
UNDER DIRECTION OF UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE, BRANCH OF PLANS AND DESIGN

ESTATE MARY POINT

NAME OF STRUCTURE
GREAT HOUSE
SAINT JOHN

VIRGIN ISLANDS

SURVEY NO.	VI-159
------------	--------

HISTORIC AMERICAN
BUILDINGS SURVEY
SHEET 5 OF 6 SHEETS

LIBRARY OF CONGRESS
STACK NUMBER

